



**QBs**

Browse

## Queue

QB5











USPAT

☒ Highlight all hit terms initially

5839788

 Failed

 Saved

-  Drafts
-  Pending
-  Active
-  Failed
-  Saved
-  Favorites
-  Tagged (32)
-  UDC
-  Queue
-  Trash

	U	1	Document ID	Issue Dat	Page	Title	Current
23	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 2622286 A	19521223	3	Trunk seal gasket	49/496.
24	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 2266703 A	19411216	4	Refrigerator cabinet	62/272
25	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 2263806 A	19411125	3	Motor vehicle	49/498.
26	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 2121826 A	19380628	5	Door jamb	49/498.
27	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 6685252 B2	20040203	6	Seal arrangement for a folding roof of a hardt	296/108
28	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 5282338 A	19940201	4	Sealing structure	49/476.
29	<input type="checkbox"/>	<input checked="" type="checkbox"/>	DE 10130405 A	20030102	6	Gap cover for vehicle sun roof is connected a	
30	<input type="checkbox"/>	<input checked="" type="checkbox"/>	EP 976596 A	20000202	6	Vehicle roof opening with light adjustment.	
31	<input type="checkbox"/>	<input checked="" type="checkbox"/>	DE 19720391 A	20020905	6	Roof of vehicle with sealing component for s	
32	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 4892351	19900109	9	Water drain trough for	296/213

EAST - [golf cart:2]

FileViewEditToolsWindowHelp

Pending

Active

Failed

Saved

L1: (185) (49/476.1).CCLS.

L2: (351) (49/495.1).CCLS.

L3: (554) (49/498.1).CCLS.

L4: (11) 11 and 12

L5: (0) (B60j010/12).CCLS.

L6: (281) B60j010/12

L7: (206) (296/213).CCLS.

L8: (29) 17 and seal and drain

L9: (1) ("5839788").PN.

(0) ("296/214.ccls.-296/224.ccls.").CCLS.

(0) ("296/\$.ccls.").CCLS.

(0) ("296/\$.ccls.").CCLS.

(0) 11 and (stop adj2 block))

(0) M.E.D.

(0) ("200/\$.ccls.").CCLS.

(0) ("188/\$.ccls.").CCLS.

(0) ("296/\$.ccls.").CCLS.

(4) golf near2 cart with solar near2 cell\$

(0) 296/110.02.ccls.-296/100.05.ccls.

(0) ("(4662115or4919473or5536060or5924760or5944373or6068327).pn.

(0) (296/146.5.ccls.).CCLS.

(0) (b60j007/00-007/22).CCLS.

(0) (b60j007/00-22).CCLS.

(0) (b60j007/00-B60j007/22).CCLS.

(199) (("49/26.ccls.") or ("49/28.ccls.")).CCLS.

(1) ("0000001").PN.

(0) ("1000001").PN.

(199) (((("49/26.ccls.") or ("49/28.ccls.")).CCLS.)

(10) (((("49/26.ccls.") or ("49/28.ccls.")).CCLS.) and (sunroof o

(744) ("318/466").CCLS.

(744) (("318/466").CCLS.)

(42) (("318/466").CCLS.) and (sunroof or roof or headliner or su

SearchListBrowseQueue

DBsUSPAT

☒ Highlight all hit terms initially

5839788

Drafts

Pending

Active

Failed

Saved

Favorites

Tagged (32)

UDC


Queue

Trash

	Type	L #	Hits	Search Text	DBs	Time Stam	Comment	Error
1	IS&R	L1	185	(49/476.1).CCLS.	USPA T	2004/03/1 8 07:26		
2	IS&R	L2	351	(49/495.1).CCLS.	USPA T	2004/03/1 8 07:43		
3	IS&R	L3	554	(49/498.1).CCLS.	USPA T	2004/03/1 8 08:27		
4	BRS	L4	11	11 and 12	USPA T	2004/03/1 8 08:29		
5	IS&R	L5	0	(B60j010/12).CCLS.	DERW ENT	2004/03/1 8 08:29		
6	BRS	L6	281	B60j010/12	DERW ENT	2004/03/1 8 09:05		
7	IS&R	L7	206	(296/213).CCLS.	USPA T	2004/03/1 8 09:05		
8	BRS	L8	29	17 and seal and drain	USPA T	2004/03/1 8 09:48		
9	IS&R	L9	1	("5839788").PN.	USPA	2004/03/1		

HisDetailsHTML

ReadyCAP|NUM|



Trash

	Type	L #	Hits	Search Text	DBs	Time Stamp	Comment	Error
2	IS&R	L2	351	(49/495.1).CCLS.	USPA T	2004/03/1 8 07:43		
3	IS&R	L3	554	(49/498.1).CCLS.	USPA T	2004/03/1 8 08:27		
4	BRS	L4	11	11 and 12	USPA T	2004/03/1 8 08:29		
5	IS&R	L5	0	(B60j010/12).CCLS.	DERW ENT	2004/03/1 8 08:29		
6	BRS	L6	281	B60j010/12	DERW ENT	2004/03/1 8 09:05		
7	IS&R	L7	206	(296/213).CCLS.	USPA T	2004/03/1 8 09:05		
8	BRS	L8	29	17 and seal and drain	USPA T	2004/03/1 8 09:48		
9	IS&R	L9	1	("5839788").PN.	USPA T	2004/03/1 8 09:48		



- ☐ Pending
- ☒ Active
  - ☒ L1: (185) (49/476.1).CCLS.
  - ☒ L2: (351) (49/495.1).CCLS.
  - ☒ L3: (554) (49/498.1).CCLS.
- ☐ Failed
  - ☒ (0) ("296/214.ccls.-296/224.ccls.").CCLS.
  - ☒ (0) ("296/\$.ccls.").CCLS.
  - ☒ (0) ("296/\$.ccls.").CCLS.
  - ☒ (0) l1 and (stop adj2 block))
  - ☒ (0) M.E.D.
  - ☒ (0) ("200/\$.ccls.").CCLS.
  - ☒ (0) ("188/\$.ccls.").CCLS.
  - ☒ (0) ("296/\$.ccls.").CCLS.
  - ☒ (4) golf near2 cart with solar near2 cell\$
  - ☒ (0) 296/110.02.ccls.-296/100.05.ccls.
  - ☒ (0) ("(4662115or4919473or5536060or5924760or5944373or6068327).pn."
  - ☒ (0) (296/146.5.ccls.).CCLS.
  - ☒ (0) (b60j007/00-007/22).CCLS.
  - ☒ (0) (b60j007/00-22).CCLS.
  - ☒ (0) (b60j007/00-B60j007/22).CCLS.
- ☐ Saved
  - ☒ (199) (("49/26.ccls.") or ("49/28.ccls.")).CCLS.
  - ☒ (1) ("0000001").PN.
  - ☒ (0) ("1000001").PN.
  - ☒ (199) (((("49/26.ccls.") or ("49/28.ccls.")).CCLS.)
  - ☒ (10) (((("49/26.ccls.") or ("49/28.ccls.")).CCLS.) and (sunroof o
  - ☒ (744) ("318/466").CCLS.
  - ☒ (744) (("318/466").CCLS.)
  - ☒ (42) (("318/466").CCLS.) and (sunroof or roof or headliner or sui
  - ☒ (2) (("5899519") or ("5927788")).PN.
  - ☒ (1) ("5927788").PN.
  - ☒ (1) ("6024396").PN.
  - ☒ (1) ("4693507").PN.
  - ☒ (268) static with build?
  - ☒ (42) (static with build?) and polyethvlene

Search List Browse Queue

DBs

USPAT

☒ Highlight all hit terms initially

49/498.1

- ☒ Drafts
- ☐ Pending
- ☒ Active
- ☐ Failed
- ☐ Saved
- ☐ Favorites
- ☒ Tagged (27)
- ☐ UDC
- ☐ Queue
- ☐ Trash

	U	1	Document ID	Issue Dat	Page	Title	Current
16	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 6332645 B1	20011225	6	Sealing arrangement for a motor vehicle sliding	296/216
17	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 6536833 B2	20030325	11	Door weather strip	296/146
18	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 3378958 A	19680423	5	Extrusions having integral portions of di	49/489.
19	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 3327429 A	19670627	3	Casket seal	49/495.
20	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 1883609 A	19321018	3	Gasket	49/495.
21	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 3360887 A	19680102	3	Extruded sealing member	49/490.
22	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 2908949 A	19591020	4	Honeycomb plastic door gasket	49/496.
23	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 2622286 A	19521223	3	Trunk seal gasket	49/496.
24	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 2266703 A	19411216	4	Refrigerator cabinet	62/272
25	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 2263806	19411125	3	Motor vehicle	49/498.

Hits

Details

HTML



Pending

Active

- L1: (185) (49/476.1).CCLS.
- L2: (351) (49/495.1).CCLS.
- L3: (554) (49/498.1).CCLS.
- L4: (11) 11 and 12
- L5: (0) (B60j010/12).CCLS.
- L6: (281) B60j010/12

Failed

- (0) ("296/214.ccls.-296/224.ccls.").CCLS.
- (0) ("296/\$.ccls.").CCLS.
- (0) ("296/\$.ccls.").CCLS.
- (0) 11 and (stop adj2 block))
- (0) M.E.D.
- (0) ("200/\$.ccls.").CCLS.
- (0) ("188/\$.ccls.").CCLS.
- (0) ("296/\$.ccls.").CCLS.
- (4) golf near2 cart with solar near2 cell\$
- (0) 296/110.02.ccls.-296/100.05.ccls.
- (0) ("(4662115or4919473or5536060or5924760or5944373or6068327).pn."
- (0) (296/146.5.ccls.).CCLS.
- (0) (b60j007/00-007/22).CCLS.
- (0) (b60j007/00-22).CCLS.
- (0) (b60j007/00-B60j007/22).CCLS.

Saved

- (199) (("49/26.ccls.") or ("49/28.ccls.")).CCLS.
- (1) ("0000001").PN.
- (0) ("1000001").PN.
- (199) (((("49/26.ccls.") or ("49/28.ccls.")).CCLS.)
- (10) (((("49/26.ccls.") or ("49/28.ccls.")).CCLS.) and (sunroof o
- (744) ("318/466").CCLS.
- (744) (("318/466").CCLS.)
- (42) (("318/466").CCLS.) and (sunroof or roof or headliner or su
- (2) (("5899519") or ("5927788")).PN.
- (1) ("5927788").PN.
- (1) ("6024396").PN.

Search List Browse Queue

DBs DERV Plurals

Default operator: ☒ Highlight all hit terms initially

B60j010/12

Drafts

Pending

Active

Failed

Saved

Favorites

Tagged (31)

UDC

Queue


Trash

	U	1	Document ID	Issue Dat	Page	Title	Current
23	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 2622286	19521223	3	Trunk seal gasket	49/496.
			A				
24	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 2266703	19411216	4	Refrigerator cabinet	62/272
			A				
25	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 2263806	19411125	3	Motor vehicle	49/498.
			A				
26	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 2121826	19380628	5	Door jamb	49/498.
			A				
27	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 6685252	20040203	6	Seal arrangement for a	296/108
			B2			folding roof of a hardt	
28	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 5282338	19940201	4	Sealing structure	49/476.
			A				
29	<input type="checkbox"/>	<input checked="" type="checkbox"/>	DE 10130405	20030102	6	Gap cover for vehicle	
			A			sun roof is connected a	
30	<input type="checkbox"/>	<input checked="" type="checkbox"/>	EP 976596 A	20000202	6	Vehicle roof opening	
						with light adjustment.	
31	<input type="checkbox"/>	<input checked="" type="checkbox"/>	DE 19720391	20020905	6	Roof of vehicle with	
			A			sealing component for s	

Hls Details HTML

Ready

[NUM]



Pending

Active

L1: (185) (49/476.1).CCLS.

L2: (351) (49/495.1).CCLS.

L3: (554) (49/498.1).CCLS.

Failed

(0) ("296/214.ccls.-296/224.ccls.").CCLS.

(0) ("296/\$.ccls.").CCLS.

(0) ("296/\$.ccls.").CCLS.

(0) 11 and (stop adj2 block))

(0) M.E.D.

(0) ("200/\$.ccls.").CCLS.

(0) ("188/\$.ccls.").CCLS.

(0) ("296/\$.ccls.").CCLS.

(4) golf near2 cart with solar near2 cell\$

(0) 296/110.02.ccls.-296/100.05.ccls.

(0) ("(4662115or4919473or5536060or5924760or5944373or6068327).pn."

(0) (296/146.5.ccls.).CCLS.

(0) (b60j007/00-007/22).CCLS.

(0) (b60j007/00-22).CCLS.

(0) (b60j007/00-B60j007/22).CCLS.

Saved

(199) (("49/26.ccls.") or ("49/28.ccls.")).CCLS.

(1) ("0000001").PN.

(0) ("1000001").PN.

(199) (((("49/26.ccls.") or ("49/28.ccls.")).CCLS.)

(10) (((("49/26.ccls.") or ("49/28.ccls.")).CCLS.) and (sunroof o

(744) ("318/466").CCLS.

(744) (("318/466").CCLS.)

(42) (("318/466").CCLS.) and (sunroof or roof or headliner or su

(2) (("5899519") or ("5927788")).PN.

(1) ("5927788").PN.

(1) ("6024396").PN.

(1) ("4693507").PN.

(268) static with build?

(42) (static with build?) and polyethvlene

Search

List

Browse

Queue

DBs

USPAT

☒ Highlight all hit terms initially

49/498.1

Drafts

Pending

Active

Failed

Saved

Favorites

Tagged (27)

UDC

Queue

Trash

	U	1	Document ID	Issue Dat	Page	Title	Current
19	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 3327429	19670627	3	Casket seal	49/495.
			A				
20	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 1883609	19321018	3	Gasket	49/495.
			A				
21	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 3360887	19680102	3	Extruded sealing member	49/490.
			A				
22	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 2908949	19591020	4	Honeycomb plastic door	49/496.
			A			gasket	
23	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 2622286	19521223	3	Trunk seal gasket	49/496.
			A				
24	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 2266703	19411216	4	Refrigerator cabinet	62/272
			A				
25	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 2263806	19411125	3	Motor vehicle	49/498.
			A				
26	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 2121826	19380628	5	Door jamb	49/498.
			A				
27	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 6685252	20040203	6	Seal arrangement for a	296/108
			B2			folding roof of a hardt	

Hits

Details

HTML

Ready

[NUM]